Lajas Valley Area, Puerto Rico 06/11/2002

Soil Map Legend

```
Map
                         Soil name
 symbol
AcD
         Aguilita clay, 5 to 20 percent slopes
AcE
         Aguilita clay, 20 to 50 percent slopes
Αg
         Aguirre clay
AmB
         Amelia-maguayo gravelly clay loams, 2 to 5 percent slopes
AmC2
         Amelia-maguayo gravelly clay loams, 5 to 12 percent slopes, eroded
Αo
         Amelia clay loam
ASB
         Americus (bahia) fine sand, 2 to 5 percent slopes
Ca
         Cartagena clay
Cc
         Cartagena silty clay loam, acid variant
         Coastal beach
Co
         Descalabrado clay loam, 2 to 12 percent slopes
DeC
DeD
         Descalabrado clay loam, 12 to 20 percent slopes
         Descalabrado clay loam, 20 to 60 percent slopes
DeF
Fe
         Fe clay
         Fraternidad clay, 0 to 2 percent slopes
FrA
FrB
         Fraternidad clay, 2 to 5 percent slopes
Ft
         Fraternidad clay, gypsum substratum
         Fraternidad clay, gravelly clay substratum, 0 to 2 percent slopes
FvA
FvB
         Fraternidad clay, gravelly clay substratum, 2 to 5 percent slopes
         Guanica clay
GC
         Guayabo fine sand
G£
         Gravel, pits and quarries
GPQ
         Guayama cherty clay loam, 5 to 20 percent slopes
GuD
GuF
         Guayama cherty clay loam, 20 to 60 percent slopes
         Jacana clay, 2 to 5 percent slopes
JaB
JaC
         Jacana clay, 5 to 12 percent slopes
JaC2
         Jacana clay, 5 to 12 percent slopes, eroded
JaD2
         Jacana clay, 12 to 20 percent slopes, eroded
         Jacana clay, calcareous substrata, 2 to 5 percent slopes
JcB
JcC
         Jacana clay, calcareous substrata, 5 to 12 percent slopes
LFD
         Landfill
Lr
         Limestone rock land
MaD2
         Mariana gravelly clay loam, 12 to 20 percent slopes, eroded
MaE2
         Mariana gravelly clay loam, 20 to 50 percent slopes, eroded
         Palmarejo loam, 0 to 2 percent slopes
Paλ
         Palmarejo loam, 2 to 5 percent slopes
PaB
PaC2
         Palmarejo loam, 5 to 12 percent slopes, eroded
PcB
         Poncena clay, 0 to 5 percent slopes
PcC2
         Poncena clay, 5 to 12 percent slopes, eroded
         Pozo blanco loam, 0 to 2 percent slopes
PoA
PzB
         Pozo blanco gravelly clay loam, 0 to 5 percent slopes
         Pozo blanco gravelly clay loam, 5 to 12 percent slopes
PzC
         Pozo blanco gravelly clay loam, 12 to 20 percent slopes
PzD
Sa
         San anton silty clay
SC
         San anton silty clay, moderately deep
Se
         San anton silty clay loam, coarse variant
SgD
         San german cobbly loam, 5 to 20 percent slopes
SqF
         San german cobbly loam, 20 to 60 percent slopes
         San german stony clay loam, 20 to 50 percent slopes
SmE
```

Lajas Valley Area, Puerto Rico

Soil Map Legend, (cont.)

Soil name Map symbol Santa isabel clay Sn SNS Soils not surveyed SoA Sosa loamy sand, 0 to 5 percent slopes $\,$ SsB Sosa sandy loam, 2 to 5 percent slopes SsD2 Sosa sandy loam, 5 to 12 percent slopes, eroded Tc Teresa clay Тf Tidal flats Ts Tidal swamp ٧a Vayas silty clay Vo Volcanic rock land W Water